



Post-Fire Repairs and alterations to The Ashenhurst-Hill Residence Construction Set


All conditions and dimensions require verification, with descrepancies to be reported to the architect



East Elevation bp3 Scale 1/4" = 1'-0"

Date: March 11 2011






Post-Fire Repairs and alterations to The Ashenhurst-Hill Residence Construction Set








Post-Fire Repairs and alterations to The Ashenhurst-Hill Residence Construction Set

All conditions and dimensions require verification, with descrepancies to be reported to the architect






Post-Fire Repairs and alterations to The Ashenhurst-Hill Residence Construction Set

All conditions and dimensions require verification, with descrepancies to be reported to the architect.








Post-Fire Repairs and alterations to The Ashenhurst-Hill Residence Construction Set

All conditions and dimensions require verification, with descrepancies to be reported to the architect.



Roof Plan

March 11 2011



Post-Fire Repairs and alterations to The Ashenhurst-Hill Residence Construction Set


All conditions and dimensions require verification, with descrepancies to be reported to the architect.




Sections A-A & B-B

• bp8

Scale 1/4" = 1'-0" North ^





Post-Fire Repairs and alterations to The Ashenhurst-Hill Residence Construction Set



Section D-D Scale 1/4" = 1'-0" North ^





Frame + Mold Natural Cotton



Frame + Mold Sand

